

# LAZER SUPER Heavy Duty Rinse Free Floor Stripper

## PRODUCT INFORMATION SHEET

### DESCRIPTION:

**LAZER SUPER** is a heavy-duty floor stripper formulated to remove heavily burnished or high build-ups of metal cross-linked sealer finishes with minimum labour. **LAZER SUPER** is safe for use on all resilient floors and quickly softens and emulsifies old worn and discoloured finishes for ease of removal.

**LAZER SUPER** must not be used to remove sealer finishes from sealed timber floors as it may affect the timber seal, requiring sanding to rectify the floor. **LAZER SUPER** is 100% volatile and therefore does not leave chemicals on the floor that could affect seals or finishes that are to be applied after stripping.

### FEATURES AND BENEFITS:

- Will remove heavily burnished or high build up of metal cross-linked sealer finishes with minimum labour.
- Safe for use on all resilient floors, quickly softens and emulsifies old worn finishes for ease of removal.
- Do not use to remove sealer finishes from timber floors – may affect timber seal.
- Rinse free - no chemical residue left on floor surface that may affect subsequent coats of floor finish.

### TECHNICAL INFORMATION:

<b>Appearance</b>	Clear water white liquid
<b>Odour</b>	Glycol
<b>pH</b>	11.5 – 12.5
<b>Specific Gravity</b>	0.980 ± 0.005
<b>Percentage Volatiles</b>	76.5 ± 0.5%
<b>Solubility in Water</b>	Infinite

### USE:

**LAZER SUPER** can be diluted up to 1 part to 4 parts with warm water, or used neat as supplied dependent upon build-up. Apply **LAZER SUPER** liberally to the floor with a cotton mop ensuring the entire floor surface is thoroughly wet. Work in small controllable area sizes.

Allow 5 – 10 minutes contact and then scrub with a slow speed rotary scrubber or Automatic Scrubber fitted with stripping pads in larger areas take care not to allow the stripper to dry off. After scrubbing, pick up the slurry, rinse with clean water and allow to dry.

On drying inspect the floor and repeat the stripping process on any areas not completely stripped.

Note: During the emulsification process most floors become very slippery.

Care should be taken when working on wet floors.

### SAFETY: Classified as Hazardous according to criteria of Worksafe Australia

#### First Aid

**Eyes:** If splashed in eyes, flush with water for 15min. Seek medical advice.

**Skin:** Wash affected area with soap and water.

**Inhalation:** If mists are inhaled, remove patient to fresh air. Seek medical advice.

**Swallowed:** Do NOT induce vomiting. Give milk or water to dilute. Seek medical advice.